522323

EP3 coated replacement spring (left side) for model 940 doors shipped from 1981 to June 1995. (door has no bearing where axle meets door bracket)

Due to product improvements, springs of different size and finish are specified for replacement in certain doors. To verify that this is the correct replacement for your application, consider the shipment date if known, and compare the original specification on the table below to the spring that you will be replacing.

Left/Right side is as observed when standing inside the storage unit looking out at the door. In standard Trac-Rite applications, the latch side is the left side.



For 940 doors from 1981 to June 1995:

Width range: 2'10" to 9'0" Height range: Up to 10'4"

	Original Spring	Replacement Spring
Wire Diameter	.225"	.234"
Inside Diameter	3.25"	3.781"
Nominal Length	9.94"	10.29"
No. of Coils	43	43
Inch Number Per Turn (IPPT)	51	51

Corresponding right side spring is 522322

THIS DRAWING AND ALL PAR	, 1
THEREOF ARE THE EXCLUSIV	
PROPERTY OF TRAC-RITE	
DOOR, INC. AND MAY NOT BE	
REPRODUCED IN WHOLE OR	
IN PART WITHOUT WRITTEN	TELY ITAC.KIIA
PERMISSION.	Trac-Rite
	214 11/11 P. 1 C. P 111 52500
314 Wilburn Road, Sun Prairie, WI 53590	
Phone: 800-448-8979 Fax: 800-236-8722	
	www.tracrite.com
DATE	
11/22/11	DESCRIPTION LEFT 1001 1005
	☐ SPRING, DOOR, LEFT, 1981-1995
BY APP'D	· · · · · · · · · · · · · · · · · · ·
SJH JL	DRAWING NO. REV. SHEET
	→ 522323 1 of 1